DEPARTMENT OF HEALTH AND HUMAN SERVICES FOOD AND DRUG ADMINISTRATION						
DISTRICT OFFICE ADDRESS AND PHONE NUMBER		DATE(S) OF INSPECTION				
12420 Parklawn Drive, Room 2032 Rockville, MD 20857		July 9-17, 2018*				
		FEI NUMBER				
Industry Information: www.fda.gov/oc/industry		3005241015				
NAME AND TITLE OF INDIVIDUAL TO WHOM REPORT IS ISSUED						
TO: Woo Sung Kee, Vice Chairman/CEO						
FIRM NAME	STREET ADDRESS					
Celltrion Inc.		23 Academy-Ro, Yeonsu-Gu				
CITY, STATE AND ZIP CODE	TYPE OF ESTABLISHMENT I					
Incheon City, 406-840, Republic of Korea	Sterile Injectable Drug	Product and Drug Subst	ance Manufacturer			
THIS DOCUMENT LISTS OBSERVATIONS MADE BY THE FDA REPRESENTATIVE(S) DURING THE INSPECTION OF YOUR FACILITY. THEY ARE INSPECTIONAL OBSERVATIONS; AND DO NOT REPRESENT A FINAL AGENCY DETERMINATION REGARDING YOUR COMPLIANCE. IF YOU HAVE AN OBJECTION REGARDING AN OBSERVATION, OR HAVE IMPLEMENTED, OR PLAN TO IMPLEMENT CORRECTIVE ACTION IN RESPONSE TO AN OBSERVATION, YOU MAY DISCUSS THE OBJECTION OR ACTION WITH THE FDA REPRESENTATIVE(S) DURING THE INSPECTION OR SUBMIT THIS INFORMATION TO FDA AT THE ADDRESS ABOVE. IF YOU HAVE ANY QUESTIONS, PLEASE CONTACT FDA AT THE PHONE NUMBER AND ADDRESS ABOVE.						
DURING AN INSPECTION OF YOUR FIRM (I) (WE) OBSERVED:						
OBSERVATION I						
There are no written procedures for production and process controls designed to assure that the drug products have the identity, strength, quality, and purity they purport or are represented to possess.  Specifically,						
Your firm failed to implement written procedures to adequately manage glass vial breakage that may occur during drug product filling operations after the vial washing step. For example, two vials were broken as documented on batch at 14:24 on April 5, 2018. The batch record states, "The debris and vials around the affected areas were removed in filling room." The record does not state how many vials were removed or any additional details. Your firm has no written procedure to ensure the vials that have the potential to be compromised with glass particles are removed from the filling line.						
In addition, the batch record for states on March 25, 2018, at "broken vials were found at the outlet of the zone" during the filling process. However, the filling operations continued until that feeds empty glass vials to the filling line. Your firm lacks adequate documentation to ensure vials that may have been compromised with glass particles did not proceed to the filling step.						
EMPLOYEE(S) SIGNATURE	EMPLOYEE(S) NAME AND TITL	E (Print or Type)	DATE ISSUED			
OF THIS N	Ashar P. Parikh, Investigato Richard Ledwidge, Biologis Jacek Cieslak, Chemist		07/17/2018			

DEPARTMENT OF HEALTH AND HUMAN SERVICES FOOD AND DRUG ADMINISTRATION					
DISTRICT OFFICE ADDRESS AND PHONE NUMBER	DATE(S) OF INSPECTION	DATE(S) OF INSPECTION			
12420 Paddam Daine Barrer 2022	July 9-17, 2018*				
12420 Parklawn Drive, Room 2032 Rockville, MD 20857	FEI NUMBER				
ROOKVIIIC, IVID 20037					
Industry Information: www.fda.gov/oc/industry	3005241015				
NAME AND TITLE OF INDIVIDUAL TO WHOM REPORT IS ISSUED					
TO: Woo Sung Kee, Vice Chairman/CEO					
FIRM NAME	STREET ADDRESS				
Celltrion Inc.	23 Academy-Ro, Yeonsu-Gu				
CITY, STATE AND ZIP CODE	TYPE OF ESTABLISHMENT INSPECTED				
Incheon City, 406-840, Republic of Korea	Sterile Injectable Drug Product and Drug S	ibstance Manufacturer			
OBSERVATION 2  Employees engaged in the processing of a drug product lack the training required to perform their assigned functions.  Specifically,  Your firm performs 100% visual inspection on finished drug product. Your qualification for the operators is inadequate in that the qualification vials with glass particles are on the of the operators is inadequate in that the operators is inadequate in the operators of the operators is inadequate in the operators of the operators of the operators is inadequate in the operator of the operators operators on the operators opera					
OBSERVATION 3					
Routine checking of automatic equipment is not performed according to a written procedure designed to assure					
proper performance.					
Specifically,					
Your firm utilizes a sensor to reject drug product vials that have not been sensor to reject drug product vials that have not been					
prior to the capping process. However, your firm does not perform challenge testing of the sensor prior					
to running batch of drug product. In addition, your firm does not document the the sensor is set to in					
the batch record.					
	51151 0/2520 11115 115 515 515 515	DATE ISSUED			
EMPLOYEE(S) SIGNATURE SEE	EMPLOYEE(S) NAME AND TITLE (Print or Type)	DATE ISSUED			
REVERSE OF THIS PAGE	Ashar P. Parikh, Investigator Richard Ledwidge, Biologist Jacek Cieslak, Chemist	07/17/2018			

DEPARTMENT OF HEALTH AND HUMAN SERVICES FOOD AND DRUG ADMINISTRATION					
DISTRICT OFFICE A	ADDRESS AND PHONE NUMBER	DATE(S) OF	INSPECTION		
	D	July 9-17	, 2018*		
Rockville, MD	n Drive, Room 2032 20857	FEI NUMBER			
Rockville, MD	20037				
	ation: www.fda.gov/oc/industry	30052410	)15		
NAME AND TITLE O	F INDIVIDUAL TO WHOM REPORT IS ISSUED				
TO: Woo Sung	Kee, Vice Chairman/CEO				
FIRM NAME		STREET ADDRESS			
Celltrion Inc.		23 Academy-Ro, Yeonsu-Gu			
CITY, STATE AND Z		TYPE OF ESTABLISHMENT INSPECTED			
Incheon City, 4	06-840, Republic of Korea	Sterile Injectable Drug Product ar	g Product and Drug Substance Manufacturer		
Procedures describing the calibration of instruments, apparatus, gauges, and recording devices are deficiently written or followed.  Specifically,  Your firm does not adequately monitor the incubator rooms used to incubate environmental, media fill, and sterility samples. Your most recent temperature mapping study determined hot and cold spots for the incubators however your routine temperature monitoring gauge is not located in these areas.					
the L b	nfirmed the presence of (b) (4) bioreactor as stated in deviation report DE	on the surface of the P2-17-170. The were fi	rst docume	culture fluid in	
OBSERVAT On July 11, 2 harvest tank	ION 6 018, during the walkthrough of the (b) (4)	unit operation, w	e observed	the transfer of	
harvest tank to the load tank is > load tank. The distance the harvest tank to the load tank is > load tank is > load tank. The distance the harvest tank to the load tank is > load tank					
and requires connecting <sub>(4)</sub> ransfer noses between the and requires connecting <sub>(4)</sub> ransfer noses between the and requires connecting <sub>(b)</sub> ransfer noses between the and requires connecting <sub>(b)</sub> ransfer noses between the					
during unit operation. The connection requires more than of open exposure because (a)					
of must be from the transfer line, prior to making the open hose connection to the (10) (4)					
In addition, your firm identified the open hose connections as the root cause for the out-of-specification bioburden result for bioburden result for bioburden load, lot# documented in Deviation DE-P2-17-167.					
	EMPLOYEE(S) SIGNATURE	EMPLOYEE(S) NAME AND TITLE (Print or Typ		DATE ISSUED	
SEE REVERSE OF THIS PAGE	THE YE	Ashar P. Parikh, Investigator Richard Ledwidge, Biologist Jacek Cieslak, Chemist		07/17/2018	

DEPARTMENT OF HEALTH AND HUMAN SERVICES FOOD AND DRUG ADMINISTRATION				
DISTRICT OFFICE ADDRESS AND PHONE NUMBER		DAT	DATE(S) OF INSPECTION	
		Jul	ly 9-17, 2018*	
12420 Parklawn Drive, Room 2032 Rockville, MD 20857				
ROCKVIIIC, IND 20037			FEI NUMBER	
Industry Information: www.fda.gov/oc/industry		300	05241015	
NAME AND TITLE OF INDIVIDUAL TO WHOM REPORT IS ISSUED				
TO: Woo Sung Kee, Vice Chairman/CEO				
FIRM NAME		STREET ADDRESS		
Celltrion Inc.		23 Academy-Ro, Yeonsu-		
CITY, STATE AND ZIP CODE		TYPE OF ESTABLISHMENT INSPE		
Incheon City, 406-840, Republic of Korea		Sterile Injectable Drug Pro	duct and Drug Subst	ance Manufacturer
OBSERVATION 7				
On July 9 2018, during the walkthrough of th	(b) (4)	unit operation in Suite (b) (c	, we observe	ed (b) (4)
On July 9, 2018, during the walkthrough of the product, formulation and excipie	nt (b) (4)	on the floor and b	bas	in. While
walking through the room, our shoe covers w	(b) (4)	to the floor which was		
excipient Your firm had no procedure	s in place t			
- (b) (4)		the final unit operation p		
and drug substance filling.	0 40 4110 10	mo mar and operation p	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	ite a moraning dag
OBSERVATION 8  During the review of QC equipment logsheet of release, stability, and reference standard sa  • (b) (4) samples from freezer LEQ-94297 (b) (4) Maintenance of Validation (MOV) on June  • (b) (4) stability samples from freezer LEQ-9429 (b) (4) MOV execution on September 19, 2017  • (b) (4) samples from freezer LEQ-93097 (b) (4) 2017  In addition, your firm had not established same exposed to room temperature for extended per	mples duri C) locate 6, 2018 255 ( <sup>(b) (4)</sup> C) located  npling hand	ng transfer between free d in Suite C2 372, were d in Suite W2 372, were d in Suite W2 3 in Suite W2 302 transfer dling procedures to ensur	zers. For example transferred to LE 607, were transfer tred to LEQ-9309 tree the frozen same	e: Q-94201 for red to FC103 for 98 on August 31, ples are not
*DATES OF INSPECTION				
7/09/2018(Mon), 7/10/2018(Tue), 7/11/2018(Wed), 7/12/2018(Thu), 7/13/2018(Fri), 7/16/2018(Mon), 7/17/2018				
(Tue)			,	
EMPLOYEE(S) SIGNATURE	E	MPLOYEE(S) NAME AND TITLE (Pri	int or Type)	DATE ISSUED
SEE REVERSE OF THIS PAGE		Ashar P. Parikh, Investigator Richard Ledwidge, Biologist Jacek Cieslak, Chemist		07/17/2018