L Loud D Dauna Tomaticator // Y			LTH AND HUMAN SERVI	CES	
Dallas, TX, 75204       Percenter         (214) 253-5200       Fax: (214) 253-5314       3011278953         Industry Information: www.fda.gov/oc/industry       3011278953         TO: Kenneth Ryan Orton, Owner       Suite 101         Prevenue       3000 NV 56th Street         Suite 101       Prevenue         Physician Preferred Medical, LLC, Suite 101       Suite 101         Constant Secon coarse       Producer of sterile drug products         This document list observations made by the FDA representative(s) during the inspection of your facility. They are inspectional observation, or have implemented, or plant to implement, corrotive action in response to an observation, you may discuss the objection erading an observation, or have implemented, or plant to implement, corrotive action in response to an observation, you may discuss the objection erading an observation, or have implemented, or plant to the preparation of testosterone and estradiol pellets. From November 1, 2014-January 30, 2015 there were approximately (b) (4) lots of Testosterone 99.57         Granulation (b) (4)       lots of testosterone pellets (varying strengths), (b) (4) lots of Estradiol 99.5% Granulation, and (b) (4)         Specifically,       a) The cleanroom (buffer room) is equipped with a direct flow of unfiltered HVAC air.         B) The ante-moon, where gowing and entry into the cleanroom cocurs, is not constructed with a supply of HEPA filtered air (1/1/1). During the ast certification of the rooms.       Div HEPA filtered air (1/1/1) lots of testosterone pellets (varying strengths), and [lots of estradiol product	DISTRICT ADDRESS AND PHON			S) OF INSPECTION	
Data 23, 14, 2000         Park (214)         253-5314         3011278953           Industry Information: www.fda.gov/oc/industry         S011278953         S011278953           The second and second					/2015*
Industry Information: www.fda.gov/oc/industry         To: Kenneth Ryan Orton, Owner         To: Kenneth Ryan Orton, Owner         Physician Preferred Medical, LLC,         Suite 101         Generation of the Street         Suite 101         Oklahoma City, OK 73112         This document lists observations made by the FDA representative(s) during the inspection of your facility. They are inspectional observations, and on terpresent a final Agency determination regarding your compliance. If you have an objection regarding your compliance. If you have any discuss the objection of services above. If you have any questions, please contact FDA at the phone number and address above.         DURING AN INSPECTION OF YOUR FIRM WE OBSERVED:         The following observations pertain to the preparation of testosterone and estradiol pellets. From November 1, 2014-January 30, 2015 there were approximately (b) (4) lots of Testosterone 99.5%         Granulation (b) (4)       lots of testosterone pellets (varying strengths), (b) (4) lots of Estradiol 99.5% Granulation, and (b) (4)         Ib separate or defined areas and control systems necessary to prevent contamination or mix-ups are deficient.         Specifically,         a) The cleanroom (buffer room) is equipped with a direct flow of unfiltered HVAC air.         b) The ante-room, where gowning and entry inot the cleanroom court, is tot constructed			1.11.2-029270		
TO:       Kenneth Ryan Orton, Owner         Physician Preferred Medical, LLC,       3300 NW 56th Street         Suite 101       Suite 101         ORVING Larcost       Suite 101         ORVING Larcost       Producer of sterile drug products         Producer of sterile drug products       Producer of sterile drug products         Dis document lists observations made by the FDA representative(s) during the inspection of your facility. They are inspectional observation, and do not represent a final Agency determination regarding your compliance. Iryou have an objection regarding an observation, you may discuss the objection or action with the FDA representative(s) during the inspection or submitted in the information to FDA at the address above. If you have any questions, please contact FDA at the phone number and address above.         DURING AN INSPECTION OF YOUR FIRM WE OBSERVED:         The following observations pertain to the preparation of testosterone and estradiol pellets. From November 1, 2014-January 30, 2015 there were approximately (b) (4) lots of Testosterone 99.5%         Granulation (b) (4)       Its of testosterone pellets (varying strengths), (b) (4) lots of Estradiol 99.5% Granulation, and (b) (4) lots of estradiol pellets (varying strengths) made.         OBSERVATION 1         The separate or defined areas and control systems necessary to prevent contamination or mix-ups are deficient.         Specifically,       a) The cleanroom (buffer room) is equipped with a direct flow of unfiltered HVAC air.         b) The ante-room, where gowring and entry into the cleanro				12/0555	
Number         Immerscore           OWNERS         Sold NM 56th Street           Suite 101         Sold NM 56th Street           Owners         Suite 101           Producer of sterile drug products           This document lists observations made by the FDA representative(s) during the inspection of your facility. They are inspectional observation, or have inplemented, or plan to implemented, plan the phone number and address above. If you have any questions, please contact FDA at the phone number and address above.           DURING AN INSPECTION OF YOUR FIRM WE OBSERVED:           The following observations pertain to the preparation of testostcrone and estradiol pellets. From November 1, 2014-January 30, 2015 there were approximately (b) (4) lots of Estostcrone 99.57%           Granulation (b) (4)         Iots of testosterone pellets (varying strengths), (b) (4) lots of Estradiol 99.55%           OBSERVATION 1           The separate or defined areas and control systems necessary to prevent contamination or mix-ups are deficient.           Specifically,           a) The cleantoom (buffer room) is equipped with a direct flow of unfiltered HVAC air.           b) To anter-from, where gowing and entry into the cleantoom occurs, is not constructed with a supply of				2 C	
Suite 101           Suite 101           OKLAHOMA City, OK 73112         Presensations and control system reserve           This document lists observations made by the FDA representative(s) during the inspection of your facility. They are inspectional observation, or have implement, or create action in response to an observation, or unay discuss the objection or action with the FDA representative(s) during the inspection or submit this information to FDA at the address above. If you have any questions, please contact FDA at the phone number and address above.           DURING AN INSPECTION OF YOUR FIRM WE OBSERVED:           The following observations pertain to the preparation of testosterone and estradiol pellets. From November 1, 2014-January 30, 2015 there were approximately (b) (4) lots of Testosterone 99.59 Granulation, (b) (4) lots of testosterone pellets (varying strengths), (b) (4) lots of Estradiol 99.5% Granulation, and (b) (4) lots of testosterone pellets (varying strengths), (b) (4) lots of Estradiol 99.5% Granulation, and (b) (4) lots of estradiol pellets. From November 1, 2014-January 30, 2015 there were approximately (b) (4) lots of Estradiol 99.5% Granulation, and (b) (4) lots of testosterone pellets (varying strengths), (b) (4) lots of Estradiol 99.5% Granulation, and (b) (4) lots of estradiol pellets. (varying strengths), (b) (4) lots of Estradiol 99.5% Granulation (b) (4) lots of were approximately (b) (4) lots of testosterone 99.59 Granulation (b) (4) lots of testosterone pellets (varying strengths), and (b) (4) lots of Estradiol 99.5% Granulation of moke studies having been performed in the cleanroom (buffer room) is equipped with a direct flow of unfiltered HVAC air.           b) The ante-room, where gowning and entry into the cleanroom cocurus, is not constructed with a supply of HEPA filtered aic 9 You	TO: Kenneth	Ryan Orton, Owner	STREET ADDRESS		
OWNER         Difference           Oklahoma City, OK 73112         Producer of sterile drug products           This document lists observations made by the FDA representative(s) during the inspection of your facility. They are inspectional observation, and do not represent final Agency determination regarding you compliance. If you have an objection regarding an observation, or have implemented, or plan to implement, corrective action in response to an observation, you may discuss the objection or action with the FDA representative(s) during the inspection or submit this information to FDA at the address above. If you have any questions, please contact FDA at the phone number and address above.           DURING AN INSPECTION OF YOUR FIRM WE OBSERVED:           The following observations pertain to the preparation of testosterone and estradiol pellets. From November 1, 2014-January 30, 2015 there were approximately (b)(4) lots of Testosterone 99.5% Granulation, and (b)(4) lots of estration pellets (varying strengths), (b)(4) lots of Estradiol 99.5% Granulation, and (b)(4) lots of estradiol pellets (varying strengths) made.           OBSERVATION 1           The separate or defined areas and control systems necessary to prevent contamination or mix-ups are deficient.           Specifically,           a) The cleanroom (buffer room) is equipped with a direct flow of unfiltered HVAC air.           b) The ante-room, where gowning and entry into the cleanroom occurs, is not constructed with a supply of HEPA filtered at io 19 uring the time period between 111/1/1 and 1/5/15, the 19 the hole A fuer free attice in the HEPA filter eddet to be replaced. Youring find to replace it until 1/0/15. Uuring the time period between 111/1/1 and 1/5/15, the 19 the	Physician Pre	eferred Medical, LLC,	3300 NW 56th St	reet	
Oklahoma City, OK 73112         Producer of sterile drug products           This document lists observations made by the FDA representative(s) during the inspection of your facility. They are inspectional observation, on have implement, or protein eaction regarding your compliance. If you have an objection regarding an observation, on have implement, or plan to implement, corrective action in response to an observation, or unay discuss the objection or action with the FDA representative(s) during the inspection or submit this information to FDA at the address above. If you have any questions, please contact FDA at the phone number and address above.           DURING AN INSPECTION OF YOUR FIRM WE OBSERVED:           The following observations pertain to the preparation of testosterone and estradiol pellets. From November 1, 2014-January 30, 2015 there were approximately (b) (4) lots of Testosterone 99.5% Granulation (b) (4) lots of testosterone pellets (varying strengths), (b) (4) lots of Estradiol 99.5% Granulation, and (b) (4) lots of testosterone pellets (varying strengths) made.           OBSERVATION 1           The separate or defined areas and control systems necessary to prevent contamination or mix-ups are deficient.           Specifically,           a) The cleanroom (buffer room) is equipped with a direct flow of unfiltered HVAC air.           b) The ante-room, where gowning and entry into the cleanroom cours, is not constructed with a supply of HEPA filtered at eo 19 Your firm failed to replace it until )/16/15. During the time period between 11/11/4 and 11/5/15, the					
This document lists observations made by the FDA representative(s) during the inspection of your facility. They are inspectional observations, and do not represent a final Agency determination regarding your compliance. If you have an objection regarding an observation, or have implemented, or plan to implement, corrective action in response to an observation, you may discuss the objection or action with the PDA representative(s) during the inspection or submit this information to FDA at the address above. If you have any questions, please contact FDA at the phone number and address above.	이 전 관계		and the former for the second s	rile drug produ	ate
observation, or have implemented, or plan to implement, corrective action in response to an observation, you may discuss the objection or action with the FDA representative(s) during the inspection or submit this information to FDA at the address above. If you have any questions, please contact FDA at the phone number and address above. DURING AN INSPECTION OF YOUR FIRM WE OBSERVED: The following observations pertain to the preparation of testosterone and estradiol pellets. From November 1, 2014-January 30, 2015 there were approximately (b) (4) lots of Testosterone 99.59 Granulation (b) (4) lots of testosterone pellets (varying strengths), (b) (4) lots of Estradiol 99.5% Granulation, and (b) (4) lots of estradiol pellets (varying strengths), (b) (4) lots of Estradiol 99.5% Granulation, and (b) (4) lots of estradiol pellets (varying strengths) made. OBSERVATION 1 The separate or defined areas and control systems necessary to prevent contamination or mix-ups are deficient. Specifically, a) The cleanroom (buffer room) is equipped with a direct flow of unfiltered HVAC air. b) The ante-room, where gowning and entry into the cleanroom occurs, is not constructed with a supply of HEPA filtered air c) Your firm does not have any documentation of smoke studies having been performed in the cleanroom (buffer room). d) During the certification of the the Pio Mood was used during the weighing, melting, granulation, sieving, and packaging with hosts of sanulated testostorone(if) of granulated estradiol) with otes of testosterone pellets (varying strengths). e) Your firm does not have a scientific rationale for performing environmental monitoring in your cleanrooms and with bods only once every (b) (4) during certification of the rooms. 1/1/1/4 and 1/5/15, the meded to be replaced. Your firm failed to replace it until 1/6/15. During the time period between 11/1/1/4 and 1/5/15, the carinelable for performing environmental monitoring of surfaces and air (viable) in the cleanroom (buffer room). During the last certification of th	This document lists of	bservations made by the FDA representative(	s) during the inspection of y	your facility. They are insp	ectional
The following observations pertain to the preparation of testosterone and estradiol pellets. From November 1, 2014-January 30, 2015 there were approximately (b) (4) lots of Testosterone 99.59 Granulation (b) (4) lots of testosterone pellets (varying strengths), (b) (4) lots of Estradiol 99.5% Granulation, and (b) (4) lots of estradiol pellets (varying strengths) made. OBSERVATION 1 The separate or defined areas and control systems necessary to prevent contamination or mix-ups are deficient. Specifically, a) The cleanroom (buffer room) is equipped with a direct flow of unfiltered HVAC air. b) The ante-room, where gowning and entry into the cleanroom occurs, is not constructed with a supply of HEPA filtered air c) Your firm does not have any documentation of smoke studies having been performed in the cleanroom (buffer room). d) During the certification of the form failed to replace it until 1/6/15. During the time period between 11/1/14 and 1/5/15, the form (b) (a) of granulated estradiol; for to replace it until 1/6/15. During the time period between 11/1/14 and 1/5/15, the form (b) (a) of granulated estradiol; for to festosterone pellets (varying strengths); and for the estradiol pellets (varying strengths). e) Your firm does not have as scientific rationale for performing environmental monitoring in your cleanrooms and form setting of granulated testosterone and settification of the rooms. f) Your firm has not established alert and action limits for environmental monitoring of surfaces and air (viable) in the cleanroom (buffer room). During the last certification in October 2014, the report stated that there were 25cfu (active air) and 5cfu (surface) found in the cleanroom and 9cfu (active air) and 7cfu (surface) found in the ante room. g) Your firm does not perform any personnel monitoring of employees involved in making the testosterone and estradiol pellets. h) The cleanroom (buffer room) and ante-room are not equipped with pressure differential indicating magnehelic gauges resulting i	observation, or have action with the FDA	implemented, or plan to implement, corrective representative(s) during the inspection or subr	action in response to an ob nit this information to FDA	servation, you may discus	s the objection or
November 1, 2014-January 30, 2015 there were approximately (b) (4) lots of Testosterone 99.59 Granulation, (b) (4) lots of testosterone pellets (varying strengths), (b) (4) lots of Estradiol 99.5% Granulation, and (b) (4) lots of estradiol pellets (varying strengths) made. OBSERVATION 1 The separate or defined areas and control systems necessary to prevent contamination or mix-ups are deficient. Specifically, a) The cleanroom (buffer room) is equipped with a direct flow of unfiltered HVAC air. b) The ante-room, where gowning and entry into the cleanroom occurs, is not constructed with a supply of HEPA filtered air c) Your firm does not have any documentation of smoke studies having been performed in the cleanroom (buffer room). d) During the certification of the 1000 (serial number (b) (4) (1015) During the time period between 11/1/14 and 1/5/15, the 1000 (serial number (b) (4) (1015) During the time period between 11/1/14 and 1/5/15, the 1000 (serial number (b) (4) (1015) During the time period between 11/1/14 and 1/5/15, the 1000 (serial number (b) (4) (1015) During the time period between 11/1/14 and 1/5/15, the 1000 (serial number (b) (4) (1015) During the time period between 11/1/14 and 1/5/15, the 1000 (serial number (b) (4) (4) (1015) During the time period between 11/1/14 and 1/5/15, the 1000 (serial number (b) (4) (1015) During the time period between 11/1/14 and 1/5/15, the 1000 (serial number (b) (4) (1015) During the time period between 11/1/14 and 1/5/15, the 1000 (serial number (b) (4) (1015) During the time period between 11/1/14 and 1/5/15, the 1000 (serial number (b) (4) (1015) During the time period between 11/1/14 and 1/5/15, the 1000 (serial number (b) (4) (1015) During the time period between 11/1/14 and 1/5/15, the 1000 (serial number (b) (4) (seriace) found in the ante room. (b) Your firm does not have a scientification of the rooms. f) Your firm does not perform any personnel monitoring of employees involved in making the testosterone and estradiol pellets. h) The	DURING AN INSPEC	TION OF YOUR FIRM WE OBSERVED:	7		
99.5% Granulation, and (b) (4)       lots of estradiol pellets (varying strengths) made.         OBSERVATION 1         The separate or defined areas and control systems necessary to prevent contamination or mix-ups are deficient.         Specifically,         a) The cleanroom (buffer room) is equipped with a direct flow of unfiltered HVAC air.         b) The ante-room, where gowning and entry into the cleanroom occurs, is not constructed with a supply of HEPA filtered air.         c) Your firm does not have any documentation of smoke studies having been performed in the cleanroom (buffer room).         d) During the certification of the 0000 hood (serial number (b)(4) on 10/30/14, the third party service reporter that the HEPA filter needed to be replaced. Your firm failed to replace it until 1/6/15. During the time period between 11/1/14 and 1/5/15, the 0000 hood was used during the weighing, melting, granulation, sieving, and packaging 0000         lots of granulated testosterone(b)(4) of granulated estradiol; 10 lots of testosterone pellets (varying strengths);       0000         e) Your firm does not have a scientific rationale for performing environmental monitoring in your cleanrooms and 0000 estradio pellets (varying strengths).       00000         e) Your firm does not have a scientific rationale for environmental monitoring of surfaces and air (viable) in the cleanroom (buffer room). During the last certification in October 2014, the report stated that there were 25cfu (active air) and 5cfu (surface) found in the alter room.       0000         g) Your firm does not perform any personnel monitoring of employees involved in making the testosterone and estrad	November 1, 20	014-January 30, 2015 there were	approximately (b)	(4) lots of Testos	terone 99.5%
OBSERVATION 1         The separate or defined areas and control systems necessary to prevent contamination or mix-ups are deficient.         Specifically,         a) The cleanroom (buffer room) is equipped with a direct flow of unfiltered HVAC air.         b) The ante-room, where gowning and entry into the cleanroom occurs, is not constructed with a supply of HEPA filtered air.         c) Your firm does not have any documentation of smoke studies having been performed in the cleanroom (buffer room).         d) During the certification of the first hood (serial number [5](4) in 10/30/14, the third party service reported that the HEPA filter needed to be replaced. Your firm failed to replace it until 1/6/15. During the time period between 11/1/14 and 1/5/15, the first periods how as used during the weighing, melting, granulation, sieving, and packaging 014         lots of granulated testosterone (b) (4) of granulated estradiol; if lots of testosterone pellets (varying strengths).       e) Your firm does not have a scientific rationale for performing environmental monitoring in your cleanrooms and first hoods only once every (b) (4) during certification of the rooms.       f) Your firm has not established alert and action limits for environmental monitoring of surfaces and air (viable) in the cleanroom (buffer room). During the last certification in October 2014, the report stated that there were 25cfu (active air) and 5cfu (surface) found in the cleanroom and 9cfu (active air) and 7cfu (surface) found in the ante room.         g) Your firm does not perform any personnel monitoring of employees involved in making the testosterone and estradiol pellets.         h) The cleanroom (buffer room) and ante-room are not equipped with pressure d					
b) The ante-room, where gowning and entry into the cleanroom occurs, is not constructed with a supply of HEPA filtered aid c) Your firm does not have any documentation of smoke studies having been performed in the cleanroom (buffer room). d) During the certification of the (0)(4) hood (serial number (b) (4) ) on 10/30/14, the third party service reported that the HEPA filter needed to be replaced. Your firm failed to replace it until 1/6/15. During the time period between 11/1/14 and 1/5/15, the (0)(4) of granulated estradiol; (16) (4) (16)(15) (16)(16)(16)(16)(16)(16)(16)(16)(16)(16)		ined areas and control systems necessary	to prevent contamination	n or mix-ups are deficie	nt.
b) The ante-room, where gowning and entry into the cleanroom occurs, is not constructed with a supply of HEPA filtered aid c) Your firm does not have any documentation of smoke studies having been performed in the cleanroom (buffer room). d) During the certification of the (0)(4) hood (serial number (b) (4) ) on 10/30/14, the third party service reported that the HEPA filter needed to be replaced. Your firm failed to replace it until 1/6/15. During the time period between 11/1/14 and 1/5/15, the (0)(4) of granulated estradiol; (16) (4) (16)(15) (16)(16)(16)(16)(16)(16)(16)(16)(16)(16)	a) The element of		C CH LUNAC		
cleanroom (buffer room). During the last certification in October 2014, the report stated that there were 25cfu (active air) and 5cfu (surface) found in the cleanroom and 9cfu (active air) and 7cfu (surface) found in the ante room. g) Your firm does not perform any personnel monitoring of employees involved in making the testosterone and estradiol pellets. h) The cleanroom (buffer room) and ante-room are not equipped with pressure differential indicating magnehelic gauges resulting in a lack of monitoring of pressure differentials during operations. There is no documentation of any monitoring by your firm of the pressure differential between the cleanroom (buffer room) and the ante room (where gowning occurs) and between the ante room and the retail pharmacy. The last room certification dated 10/30/14 reported that the cleanroom SEE REVERSE Margaret M Annes, Investigator Maggaret M annes, 10/2/19/201	<ul> <li>b) The ante-room, y</li> <li>c) Your firm does r</li> <li>d) During the certification that the HEPA filtee</li> <li>11/1/14 and 1/5/15, lots of granulated to estradiol pellets (value) Your firm does r</li> </ul>	where gowning and entry into the cleanro tot have any documentation of smoke stud- ication of the $(0)(4)$ hood (serial nu- r needed to be replaced. Your firm failed the $(0)(4)$ hood was used during the estosterone $(b)(4)$ of granulated estradiol; rying strengths).	om occurs, is not constru- dies having been perform imber (b) (4) ) on 1 to replace it until 1/6/15 ne weighing, melting, gra lots of testosterone per ng environmental monit	acted with a supply of H and in the cleanroom (bu 0/30/14, the third party b. During the time period anulation, sieving, and p ellets (varying strengths)	affer room). service reported d between packaging <sup>(D)(4)</sup> ); and <sup>(D)</sup> lots of
cleanroom (buffer room). During the last certification in October 2014, the report stated that there were 25cfu (active air) and 5cfu (surface) found in the cleanroom and 9cfu (active air) and 7cfu (surface) found in the ante room. g) Your firm does not perform any personnel monitoring of employees involved in making the testosterone and estradiol pellets. h) The cleanroom (buffer room) and ante-room are not equipped with pressure differential indicating magnehelic gauges resulting in a lack of monitoring of pressure differentials during operations. There is no documentation of any monitoring by your firm of the pressure differential between the cleanroom (buffer room) and the ante room (where gowning occurs) and between the ante room and the retail pharmacy. The last room certification dated 10/30/14 reported that the cleanroom SEE REVERSE Margaret M Annes, Investigator Maggaret M annes, 10/2/19/201				of surfaces and air (vial	ole) in the
g) Your firm does not perform any personnel monitoring of employees involved in making the testosterone and estradiol pellets. h) The cleanroom (buffer room) and ante-room are not equipped with pressure differential indicating magnehelic gauges resulting in a lack of monitoring of pressure differentials during operations. There is no documentation of any monitoring by your firm of the pressure differential between the cleanroom (buffer room) and the ante room (where gowning occurs) and between the ante room and the retail pharmacy. The last room certification dated 10/30/14 reported that the cleanroom <b>SEE REVERSE</b> Margaret M Annes, Investigator Margaret M. Annes	cleanroom (buffer r	oom). During the last certification in Oct	tober 2014, the report sta	ited that there were 25c	
pellets. h) The cleanroom (buffer room) and ante-room are not equipped with pressure differential indicating magnehelic gauges resulting in a lack of monitoring of pressure differentials during operations. There is no documentation of any monitoring by your firm of the pressure differential between the cleanroom (buffer room) and the ante room (where gowning occurs) and between the ante room and the retail pharmacy. The last room certification dated 10/30/14 reported that the cleanroom <b>SEE REVERSE</b> Margaret M Annes, Investigator Margaret M. Cannes Lloud D. Brupo, Investigator Margaret M. 2019/201					
h) The cleanroom (buffer room) and ante-room are not equipped with pressure differential indicating magnehelic gauges resulting in a lack of monitoring of pressure differentials during operations. There is no documentation of any monitoring by your firm of the pressure differential between the cleanroom (buffer room) and the ante room (where gowning occurs) and between the ante room and the retail pharmacy. The last room certification dated 10/30/14 reported that the cleanroom <b>SEE REVERSE</b> Margaret M Annes, Investigator Margaret M. Convestigator M. Convest	g) i our firm does n pellets	ot perform any personnel monitoring of e	employees involved in m	aking the testosterone a	nd estradiol
resulting in a lack of monitoring of pressure differentials during operations. There is no documentation of any monitoring by your firm of the pressure differential between the cleanroom (buffer room) and the ante room (where gowning occurs) and between the ante room and the retail pharmacy. The last room certification dated 10/30/14 reported that the cleanroom SEE REVERSE Margaret M Annes, Investigator Margaret M Annes, Investigator Margaret M (Margaret M Annes), Investigator Margaret M (Margaret M (Margaret M Margaret M (Margaret M (M	COMPAREMENT	ouffer room) and ante-room are not equip	ped with pressure different	ential indicating magnel	nelic gauges
SEE REVERSE Margaret M Annes, Investigator Margaret M. Connes, 202/19/201	resulting in a lack o	f monitoring of pressure differentials dur	ing operations. There is	no documentation of an	y monitoring by
SEE REVERSE Margaret M Annes, Investigator Margaret M. annos					
SEE REVERSE Margaret M Annes, Investigator Margaret M. annes	between the ante ro	1960 A	m certification dated 10/	30/14 reported that the	and the second se
Lloyd D Payme Trunctigator ()		ALC: THE REAL PROPERTY AND ALC:	ma	m	DATE ISSUED
	SEE REVERSE OF THIS PAGE		r an	m, cennos	02/19/2015
FORM FDA 483 (09/08) PREVIOUS EDITION OBSOLETE INSPECTIONAL OBSERVATIONS PAGE 1 OF 7 PAGE	FORM FDA 483 (09/08)		ECTIONAL OBSERVATIO	NIC	PAGE 1 OF 7 PAGES

		TH AND HUMAN SERVICES	
DISTRICT ADDRESS AND PHO		G ADMINISTRATION DATE(S) OF INSPECTION	
	entral Expressway, Suite 300	02/03/2015 - 02/1	9/2015*
Dallas, TX (214) 253-52	75204 00 Fax:(214) 253-5314	3011278953	
	ormation: www.fda.gov/oc/indu		
TO: Kenneth	Ryan Orton, Owner	STREET ADDRESS	
Physician Pro	eferred Medical, LLC,	3300 NW 56th Street	
		Suite 101	
CITY, STATE, ZIP CODE, COUN Oklahoma Cit	05804	TYPE ESTABLISHMENT INSPECTED Producer of sterile drug prod	note
OKTAHOMA CIL	Y, OK 73112	FIGURCEI OF SCETTLE drug proc	luces
(buffer room) does certification. i) The exhaust ven j) Re-certification	not meet the minimum pressure differenties to for the cleanroom (buffer room) exits (b)		the 10/30/14
OBSERVATION			
	ed to prevent microbiological contaminatio erilization process.	n of drug products purporting to be sterile do	not include
prepares testostero non-sterile vials w (b) (4) used (b	ne and estradiol pellets of varying strength ith screw-top lids, and then (b) (4) and then	ess for any of the drug products that you prep s from bulk non-sterile APIs and excipients, h. Your firm has no documentation of the qu or how the (b) (4) for the pellets was deve hknown), your (b) (4) that you started using (date	places them into alification of the loped. Per your
OBSERVATION	3		
	o thoroughly review any unexplained discre cifications whether or not the batch has bee	epancy and the failure of a batch or any of its on already distributed.	components to
Specifically,			
7/7/14 & 7/8/14 an by your firm into the take an "Aseptic Tar b) The last environ microbiological co- report states that via active air. The acti- firm into this failur disinfectant used fr	d was recalled by your firm on 7/24/14. The sterility failure and no corrective actions echnique Self-Assessment" exam. mental monitoring of your cleanroom (buffer ntamination in your cleanroom (buffer room able environmental sampling "requires atted on limit listed in the report is(b) (4). The e and how this may impact product. Your om (b) (4)	n 7/7/14 failed sterility. Part of the lot had b here is no documentation of an investigation implemented with the exception of having y fer room) by a third party in October 2014, re n) that were considered above action level puntion." Counts in the cleanroom (buffer room here is no documentation of an investigation p Pharmacist stated that after the report you ch the corrective action was effective. anroom dated 10/30/14 states that the hood w	being performed your employees evealed levels of er the report. The m) were 25CFU for performed by your anged the itoring was
	EMPLOYEE(S) SIGNATURE		DATE ISSUED
SEE REVERSE OF THIS PAGE	Margaret M Annes, Investigat Lloyd D. Payne, Investigator		02/19/2015
FORM FDA 483 (09/08)	PREVIOUS EDITION OBSOLETE INSPE	CTIONAL OBSERVATIONS	PAGE 2 OF 7 PAGES

		TH AND HUMAN SERVICES G ADMINISTRATION	
DISTRICT ADDRESS AND PHO		DATE(5) OF INSPECTION	
	entral Expressway, Suite 300	02/03/2015 - 02/19	/2015*
	00 Fax:(214) 253-5314	FEI NUMBER 3011278953	
Industry Inf	ormation: www.fda.gov/oc/indu JAL TO WHOM REPORT ISSUED	stry	
	Ryan Orton, Owner		
FIRM NAME	eferred Medical, LLC,	STREET ADDRESS 3300 NW 56th Street	
CITY, STATE, ZIP CODE, COU		Suite 101	
	y, OK 73112	TYPE ESTABLISHMENT INSPECTED Producer of sterile drug produ	cts
velocity. Filter ne documentation of failure in October estradiol, (b) (4) were produced.	eeds to be replaced ASAP." Your firm did to an investigation by your firm into the failur 2014 until it was changed on 1/6/15, (b) (4 lots of testosterone pellets (varying str	"device does not meet the minimum requirement to change the HEPA filter until 1/6/15. There e of the filter or any product impact. From the lots of granulated testosterone, (b) (4) of rengths), and (b) (4) lots of estradiol pellets (v	is no date of the initial granulated
OBSERVATION	4	*	
Written procedure manufacture, proc	s are not established for the cleaning and m essing, packing or holding of a drug produc	aintenance of equipment, including utensils, us t.	sed in the
Specifically,			
to make testostero b) Your firm is usi testosterone and ex (b) (4) c) Your firm is usi d) Your firm is no	stradiol pellets. The non-sterile wipes are u , ng non-sterile (b) (4)	and disinfecting the equipment used to prepare sed on all equipment used to make the pellets i to clean the (b) (4) cific cleaning agents and disinfectants used on	ncluding the
OBSERVATION There is a lack of y detail the methods		providing cleaning schedules, and describing i itation.	n sufficient
Specifically,			
and estradiol pelle b) Your firm is usi wipes are used on c) Your firm is usi and to clean the d) Your firm is not	ng non-sterile(b) (4) wipes when cleaning the floors, walls and ceilings of the cleanroung non-sterile(b) (4) (0)(4) hoods.	and disinfecting the cleanroom (buffer room).	The non-sterile
	EMPLOYEE(6) SIGNATURE	17525	DATE ISSUED
SEE REVERSE OF THIS PAGE	Margaret M Annes, Investigat Lloyd D. Payne, Investigator		
OF THISTAGE	hioya b. rayne, investigator	×	02/19/2015

DEPARTMENT OF HEALTH AND HUMAN SERVICES FOOD AND DRUG ADMINISTRATION				
DISTRICT ADDRESS AND PHONE NUMBER	DATE(S) OF INSPECTION			
4040 North Central Expressway, Suite 300	02/03/2015 - 02/19/2015*			
Dallas, TX 75204	FEINUMBER			
(214) 253-5200 Fax: (214) 253-5314	3011278953			
Industry Information: www.fda.gov/oc/indu	stry			
NAME AND TITLE OF INDIVIDUAL TO WHOM REPORT ISSUED				
TO: Kenneth Ryan Orton, Owner				
FIRM NAME	STREET ADDRESS			
Physician Preferred Medical, LLC,	3300 NW 56th Street			
	Suite 101			
CITY, STATE, ZIP CODE, COUNTRY	TYPE ESTABLISHMENT INSPECTED			
Oklahoma City, OK 73112	Producer of sterile drug products			

### **OBSERVATION 6**

Clothing of personnel engaged in the manufacturing and processing of drug products is not appropriate for the duties they perform.

Specifically, the general gowning attire for entry into the cleanroom (buffer room) where testosterone and estradiol pellets are made consists of the following: scrubs worn from outside the facility, a disposable lab coat, a single hair net, a surgical face mask with ties and booties. All are non-sterile. The operators use sterile gloves. The general gowning requirements leave exposed skin around the eyes, forehead, and neck of the person preparing the drug product. Your firm does not have a scientific rationale for your gowning requirements.

#### **OBSERVATION 7**

Container closure systems do not provide adequate protection against foreseeable external factors in storage and use that can cause deterioration or contamination of the drug product.

Specifically, your firm packages the testosterone and estradiol pellets into non-sterile/non-depyrogenated 2mL amber glass vials with a screw top lid. Your firm has no documentation to show that this packaging and container/closure system is suitable to protect the drug product from external factors that may affect the quality and sterility of the drug product over time.

# **OBSERVATION 8**

Drug product containers and closures were not sterilized and processed to remove pyrogenic properties to assure that they are suitable for their intended use.

Specifically, your firm packages the testosterone and estradiol pellets into non-sterile/non-depyrogenated 2mL amber glass vials with a screw top lid that are (b) (4) Your firm does not process the vials and screw-top lids prior to packaging to remove pyrogenic properties. Your firm has not validated the (b) (4) for the pellets and has no documentation to show that the vials and screw-top lids are (b) (4).

#### **OBSERVATION 9**

Buildings used in the manufacture, processing, packing, or holding of a drug product do not have the suitable construction to facilitate cleaning, maintenance, and proper operations.

Specifically,

	cleanroom (buffer room) is constructed of (b) (4) e cleanroom (buffer room) is constructed of (b) (4)	
	EMPLOYEE(8) SIGNATURE	DATE ISSUED
SEE REVERSE OF THIS PAGE	Margaret M Annes, Investigator Margaret M. Cinnes Lloyd D. Payne, Investigator	02/19/2015
FORM FDA 483 (09/08)	PREVIOUS EDITION OBSOLETE INSPECTIONAL OBSERVATIONS	PAGE 4 OF 7 PAGES

	HEALTH AND HUMAN DRUG ADMINISTRATION	
DISTRICT ADDRESS AND PHONE NUMBER		DATE(S) OF INSPECTION
4040 North Central Expressway, Suite 3	00	02/03/2015 - 02/19/2015*
Dallas, TX 75204		FEI NUMBER
(214) 253-5200 Fax: (214) 253-5314		3011278953
Industry Information: www.fda.gov/oc/i	ndustry	
NAME AND TITLE OF INDIVIDUAL TO WHOM REPORT ISSUED		
TO: Kenneth Ryan Orton, Owner		
FIRM NAME	STREET ADDRESS	
Physician Preferred Medical, LLC,	3300 NW 56	oth Street
	Suite 101	
CITY, STATE, ZIP CODE, COUNTRY	TYPE ESTABLISHMENT	INSPECTED
Oklahoma City, OK 73112	Producer c	of sterile drug products
*		

#### (b) (4)

There is a noticeable lip between the (b) (4)

that allows for the collection of production dust and airborne particulates. Also, (b) (4) do not totally enclose the circumference of (b) (4) allowing open access directly into the cleanroom (buffer room) from the adjoining unclassified areas above and about.

#### **OBSERVATION 10**

Laboratory controls do not include the establishment of scientifically sound and appropriate specifications and test procedures designed to assure that drug products conform to appropriate standards of identity, strength, quality and purity.

Specifically, your firm has not defined all specifications for the release of each lot of drug products prepared by your firm. Your firm has not determined endotoxin limits for your pellet products (testosterone and estradiol), drug release rate, or any other physical quality outside of potency that might affect the quality of the pellets.

#### **OBSERVATION 11**

Testing and release of drug product for distribution do not include appropriate laboratory determination of satisfactory conformance to the final specifications and identity and strength of each active ingredient prior to release.

Specifically, your firm does not conduct potency testing for all lots of sterile drug products produced. Your firm only performs potency testing on (b) (4) of pellets (testosterone and estradiol) produced from a lot of granulation.

#### **OBSERVATION 12**

There is no written testing program designed to assess the stability characteristics of drug products.

Specifically, your firm does not have a written stability testing program to justify the Beyond Use Date (BUD) of 180 days placed on your testosterone and estradiol pellets. In addition to that, the BUD assigned to some lots of pellets exceeds the expiration date/retest date of the active pharmaceutical ingredient (API) used. For example, the expiration date for lot #(D)(4) of Testosterone, USP (soy) per the Certificate of Analysis from your vendor is 2/28/15. This lot of API was used in lot #11251401 of Testosterone #(D)(4). Lot #11251401 was in turn used to make lot #s 120114P (100mg), 120314R (200mg) and 120814S (25mg) of testosterone pellets. The BUD assigned to these lots was 05/15.

#### **OBSERVATION 13**

Each batch of drug product required to be free of objectionable microorganisms is not tested through appropriate laboratory testing.

Specifically, your firm does not perform endotoxin testing or (b) (4) of pellets (testosterone or estradiol) made from a new lot of granulation.

SEE REVERSE OF THIS PAGE	EMPLOYEE(B) SIGNATURE Margaret M Annes, Investigator Margaret M. Cinnes Lloyd D. Payne, Investigator	DATE ISSUED
FORM FDA 483 (09/08)	INSPECTIONAL OBSERVATIONS	PAGE 5 OF 7 PAGES

	LTH AND HUMAN SERVICES
DISTRICT ADDRESS AND PHONE NUMBER	DATE(S) OF INSPECTION
4040 North Central Expressway, Suite 300	02/03/2015 - 02/19/2015*
Dallas, TX 75204	FEINUMBER
(214) 253-5200 Fax:(214) 253-5314	3011278953
Industry Information: www.fda.gov/oc/indu	istry
NAME AND TITLE OF INDIVIDUAL TO WHOM REPORT ISSUED	
TO: Kenneth Ryan Orton, Owner	
FIRM NAME	STREET ADDRESS
Physician Preferred Medical, LLC,	3300 NW 56th Street
	Suite 101
CITY, STATE, ZIP CODE, COUNTRY	TYPE ESTABLISHMENT INSPECTED
Oklahoma City, OK 73112	Producer of sterile drug products
	at they do not include complete manufacturing and procedures. for the testosterone and estradiol pellets the sterilization $(b)(4)$ to hknown) your firm purchased a new (b) (4) that has the

capability to (b) (4) Prior to that time your firm has no documentation of the sterilization of any lots of pellets produced. From November 1, 2014-January 14, 2015 your firm made approximately of lots of testosterone pellets (varying strengths) and of lots of estradiol pellets (varying strengths) for which there is no documentation of the lot.

### **OBSERVATION 15**

Written production and control procedures include batches formulated with the intent to provide less than 100 percent of the labeled or established amount of active ingredient.

Specifically, your firm does not formulate your testosterone and estradiol pellets to provide for 100% of label claim. Your firm formulates the pellets to contain (0)(4) of the active ingredient.

#### **OBSERVATION 16**

Routine calibration and checking of electronic equipment is not performed according to a written program designed to assure proper performance.

Specifically,

a) The (b) (4) electronic balance certification last performed on 8/8/14, did not include specific balance identifications and the certification stickers were placed on a sheet of paper instead of on the balances.

b) The (b) (4) electronic balances (models(b) (4) ) used to weigh the active pharmaceutical ingredients (testosterone and estradiol); the (b) (4) and the finished product (testosterone and estradiol) pellets are not calibrated within their intended range of use (b) (4) . The latest certification dated 8/8/14 certified them as a "counter scale over 10lbs" and the actual weight used during the certification was not documented. c) The (b) (4) electronic balances (models (b) (4) ) used to weigh the active pharmaceutical ingredients (b) (4) , and the finished product pellets are not checked prior to use to verify they remain accurate following their relocation from the storage table to the (9)(4) hoods or from side to side within the (9)(4) hoods each time

following their relocation from the storage table to the (0)(4) hoods or from side to side within the (0)(4) hoods each time a batch of pellets is made.

	EMPLOYEE(5) SIGNATURE	DATE ISSUED
SEE REVERSE OF THIS PAGE	Margaret M Annes, Investigator Margaret M. anna Lloyd D. Payne, Investigator	02/19/2015

FORM FDA 483 (09/08)

# PREVIOUS EDITION OBSOLETE

# INSPECTIONAL OBSERVATIONS

PAGE 6 OF 7 PAGES

DEPARTMENT OF H	ALTH AND HUMAN SERVICES		
FOOD AND I	RUG ADMINISTRATION	2704	
DISTRICT ADDRESS AND PHONE NUMBER 4040 North Central Expressway, Suite 300		DATE(S) OF INSPECTION 02/03/2015 - 02/19/2015*	
Dallas, TX 75204 (214) 253-5200 Fax:(214) 253-5314 Industry Information: www.fda.gov/oc/in	30112789	53	
NAME AND TITLE OF INDIVIDUAL TO WHOM REPORT ISSUED TO: Kenneth Ryan Orton, Owner FIRM MAME			
Physician Preferred Medical, LLC,	3300 NW 56th Street Suite 101		
CITY, STATE, ZIP CODE, COUNTRY	TYPE ESTABLISHMENT INSPECTED		
Oklahoma City, OK 73112	Producer of sterile	drug products	
e) 20mg: (b) (4) (lot 12161401-121714V), f) 22mg: (b) (4) (lot 01131501-011415E) and (b) (4) (lot 14	A review of batch records from 1 s follows:		
Equipment used in the manufacture, processing, packing or operations for its cleaning and maintenance.	holding of drug products is not of	f appropriate design to facilitate	
Specifically, the work tables used to hold the two (b)(4) that are not easily cleanable.	oods in the cleanroom (buffer roo	m) are constructed of (b) (4)	
* DATES OF INSPECTION: 02/03/2015(Tuc), 02/04/2015(Wed), 02/05/2015(Thu), 02/10/201	(Tue), 02/13/2015(Fri), 02/17/2015(	Tue), 02/19/2015(Thu)	

		DATE ISSUED
SEE REVERSE OF THIS PAGE	Margaret M Annes, Investigator Margaret M. Cinnes Lloyd D. Payne, Investigator	02/19/2015
FORM FDA 483 (09/08)	PREVIOUS EDITION OBSOLETE INSPECTIONAL OBSERVATIONS	PAGE 7 OF 7 PAGES