-	R			The and approximate	
		ALTH AND HUMAN SERVICE	ES .		
DISTRICT OFFICE ADDRESS AND PHONE NUMBER			DATE(S) OF INSPECTION		
Kansas City District Office/Division of Pharmaceutical Quality Operations III 8050 Marshall Drive, Suite 205 Lenexa, KS 66214		Operations III	07/10/2017 -07/27/20	17	
			FEINUMBER		
Phone: (913) 495-5100 Industry Information: www.fda.gov/oc/industry			3003718003		
	DF INDIVIDUAL TO WHOM REPORT IS ISSUED				
TO: Seth A V	anek, Pharmacist in Charge				
FIRM NAME STREET ADDRESS			1 . (1-12)	21000212380510	
Essential Pharmacy Compounding LLC 620 N. 114th St.		620 N. 114th St.			
CITY, STATE AND ZIP CODE			TYPE OF ESTABLISHMENT INSPECTED		
Omaha, NE 68	A, NE 68154-1571 Producer of Sterile and Non-Sterile Drugs				
THIS DOCUMENT LISTS OBSERVATIONS MADE BY THE FDA REPRESENTATIVE(S) DURING THE INSPECTION OF YOUR FACILITY. THEY ARE INSPECTIONAL OBSERVATIONS; AND DO NOT REPRESENT A FINAL AGENCY DETERMINATION REGARDING YOUR COMPLIANCE. IF YOU HAVE AN OBJECTION REGARDING AN OBSERVATION, OR HAVE IMPLEMENTED, OR PLAN TO IMPLEMENT CORRECTIVE ACTION IN RESPONSE TO AN OBSERVATION, YOU MAY DISCUSS THE OBJECTION OR ACTION WITH THE FDA REPRESENTATIVE(S) DURING THE INSPECTION OR SUBMIT THIS INFORMATION TO FDA AT THE ADDRESS ABOVE. IF YOU HAVE ANY QUESTIONS, PLEASE CONTACT FDA AT THE PHONE NUMBER AND ADDRESS ABOVE.					
DURING AN INSPE	CTION OF YOUR FIRM (I) (WE) OBSERVED:				
Observation	1				
Equipment, materials, and/or supplies are not cleaned prior to initiating aseptic production after the performance of smoke studies. Specifically, the base for the smoke used in the study is (b) (4). There is no documented cleaning after the smoke study to remove residues from (b) (4). There is no verification check to ensure the removal of (b) (4) from the ISO 5 laminar flow hood after the completion of the smoke study.					
Observation	-				
Personnel engaged in aseptic processing failed to prevent cross-contamination on the working surface of the ISO 5 laminar flow hood work bench.					
Specifically, a Technician was observed in the aseptic production room using a sterile wipe to clean her gloved hands between compounding different products; also, she used the same wipe to clean the ISO 5 hood work bench. This practice could lead to possible product contamination.					
			to be	1	
	Add Continuation Page				
	EMPLOYEE(S) SIGNATURE	EMPLOYEE(S) NAME AND TITLE	E (Print or Type)	DATE ISSUED	
SEE REVERSE OF THIS PAGE	Kellia N. Hicks –S Device of the other states of the state	Kellia N Hicks, Investigator		07/27/2017	
FORM FDA 483 (9	/08) PREVIOUS EDITION OBSOLETE	INSPECTIONAL OBSERVA	TIONS	Page 1 of 2	

	HEALTH AND HUMAN SERVI	CES				
DISTRICT OFFICE ADDRESS AND PHONE NUMBER Kansas City District Office/Division of Pharmaceutical Quali 8050 Marshall Drive, Suite 205 Lenexa, KS 66214	ty Operations III	DATE(S) OF INSPECTION 07/10/2017 -07/27/20 FEI NUMBER	17			
Phone: (913) 495-5100						
Industry Information: www.fda.gov/oc/industry		3003718003				
NAME AND TITLE OF INDIVIDUAL TO WHOM REPORT IS ISSUED						
TO: Seth A. Vanek, Pharmacist in Charge						
FIRM NAME	STREET ADDRESS					
Essential Pharmacy Compounding LLC	620 N. 114th St.					
CITY, STATE AND ZIP CODE	TYPE OF ESTABLISHMENT INSPECTED					
Omaha, NE 68154-1571	Producer of Sterile a	and Non-Sterile Drugs				
Observation 3 Non-sterile disinfecting agents are used in the aseptic processing (ISO 5) area.						
Specifically, For example, Disinfectants,	(b)	(4) are diluted with	(b) (4) and			
		Ad	ld Continuation Page			
EMPLOYEE(S) SIGNATURE	EMPLOYEE(S) NAME AND TH	1992) 	DATE ISSUED			
SEE PAGE OF THIS PAGE Kellin Hicks	Kellia N Hicks, Investigat	or	07/27/2017			
FORM FDA 483 (9/08) PREVIOUS EDITION OBSOLETE	INSPECTIONAL OBSERV	ATIONS	Page 2 of 2			