

Rev 1: April 2022

FSN Ref: 22-0002

Date: April 1, 2022

### <u>Urgent Medical Device Recall Notice</u> Certain KARL STORZ Flexible Endoscopes for Urological Use

**For Attention of:** Representatives for medical product safety, users, operators, importers, distributors

Commercial name(s): See Appendix

Device Model/Catalogue/part numbers : See Appendix

Affected serial numbers: All serial numbers of devices listed

FSN Type: New FSN, Ref.: 22-0002

#### I. Identification of Affected Devices

The flexible endoscopes subject to this Recall Notice are single channel endoscopes with an attached T-Luer that are intended for various urological indications for diagnostic and therapeutic use and that contain recommended methods of high-level disinfection and liquid chemical sterilization in their instructions for use.

#### II. Reason for the Medical Device Recall Notice

#### a. Description of the product problem

This Recall Notice describes a labeling update to correct the instructions for use for the flexible urological endoscopes identified in the Appendix to advise that high-level disinfection and, for specific models, liquid chemical sterilization should not be used as methods of reprocessing. Customers that do not have access to an appropriate sterilization method recommended in the applicable instructions for use for these endoscopes should discontinue use of the endoscopes and return them to KARL STORZ as described below.

#### b. Background of the issue

Supplemental validation testing of the efficacy of the manual high-level disinfection process was performed. Testing showed that the required efficacy level of disinfection was not achieved. To the extent included in the current applicable instructions for use, the following reprocessing methods are being removed from the instructions for use of the affected endoscopes.

- Manual High-Level Disinfection:
  - o Cidex-OPA
  - o Revital-Ox™ RESERT® (e.g., 2.0% Accelerated Hydrogen Peroxide solution).
- Automated High-Level Disinfection via an Automated Endoscope Reprocessor:
  - Medivators AER
  - Reliance EPS
  - EvoTech ECR



- Liquid Chemical Sterilization (see Appendix for specific models):
  - o STERIS System 1E

#### c. Hazard giving rise to the notice

As the efficacy of the manual high-level disinfection process cannot be assured for the affected products, there is a risk that the patient may be exposed to a higher risk of infection. You should discontinue use of high-level disinfection as a method of reprocessing the affected endoscopes and, for specific models as designated in the Appendix, discontinue liquid chemical sterilization as well.

#### d. Risks to patient/user or third parties

The use of a flexible endoscope that is incompletely reprocessed with an ineffective disinfection or sterilization cycle has a potential to transmit a patient infection.

#### III. Type of Action to mitigate the risk

#### a. Action to be taken by the user

- Immediately discontinue the use of all high-level disinfection methods for all affected endoscopes. For specific models designated in the Appendix, also discontinue liquid chemical sterilization as a method of reprocessing.
- 2. The affected endoscopes should be **sterilized after each use** by an appropriate sterilization method recommended in the instructions for use specific to each endoscope (which, for specific models designated in the Appendix, does not include liquid chemical sterilization).
- 3. If your facility does not have access to an appropriate sterilization method recommended in the applicable instructions for use, immediately discontinue use of the affected endoscopes. KARL STORZ will provide you with instructions for returning your endoscopes upon receipt of your completed Acknowledgment Form.
- 4. Ensure that all relevant personnel in your organization review this Urgent Medical Device Recall Notice. To help ensure that the affected endoscopes are sterilized after each use using an appropriate method, please direct the personnel responsible for reprocessing in your organization to maintain and rely upon this Urgent Medical Device Recall Notice in the same manner that they would other reprocessing instructions until updated instructions for use are available for the affected endoscopes.
- 5. KARL STORZ anticipates that updated instructions for use for affected endoscopes reflecting the changes described in this Urgent Medical Device Recall Notice will be available by April 18, 2022 at <a href="https://spwebspace.karlstorz.com/sites/HLDCorrection/SitePages/Home.aspx">https://spwebspace.karlstorz.com/sites/HLDCorrection/SitePages/Home.aspx</a>. Once the updated instructions for use are available, please discard any prior versions of the instructions for use for the affected endoscopes that you may possess.
- 6. If you have sold or transferred any of the affected endoscopes to third parties, please promptly forward this letter to all such third parties.
- 7. Please legibly complete the enclosed Acknowledgment Form and return it as soon as possible via the contact information specified on the form.

#### b. Action being taken by the manufacturer

KARL STORZ is updating the instructions for use of the affected endoscopes to remove all high-level disinfection methods and, for specific models as designated in the Appendix, liquid chemical sterilization. These updated instructions for use will be made available as described above.

Please maintain awareness of this notice and the requested actions for an appropriate period to ensure effectiveness of the corrective action.

Please notify KARL STORZ of any adverse events or quality problems associated with your use of the affected endoscopes. Adverse events or quality problems may also be reported to FDA's MedWatch Adverse Event Reporting program.

If you have any questions regarding this action, please use the contact information provided below:



**Telephone:** 1-888-352-9616 1-888-912-7088 karlstorz<sup>7044</sup> Fax:

E-Mail: karlstorz7041@sedgwick.com

On behalf of KARL STORZ, we thank you for your help and apologize for any inconvenience.

Sincerely,

KARL STORZ Endoscopy-America, Inc.



### **ACKNOWLEDGMENT FORM**

## **Urgent Medical Device Recall Notice – 22-0002**

Please complete this form and return it to us by faxing it to 1-888-912-7088 or emailing it to karlstorz7041@sedgwick.com. Please check all applicable boxes.

to ka	arlstorz7041@sedgw	ick.com. Please check all applicable boxes.					
	I confirm that I have r and completed all act	ead and understood the "Urgent Medical Device Recall Notice" ions requested.					
Ch	eck one of the two box	kes below.					
	My facility will sterilize the affected flexible endoscopes after each use by an appropriate sterilization method recommended in the applicable instructions for use and this Urgent Medical Device Recall Notice and will implement a procedure to ensure the affected scopes are not reprocessed through high-level disinfection or, a applicable, through liquid chemical sterilization.						
		ave access to an appropriate sterilization method recommended uctions for use and will discontinue use of the affected scopes.					
Number of scopes to be returned:							
	Upon receipt of your completed Acknowledgment Form, KARL STORZ will provide you with instructions for returning your endoscopes.						
Ch	eck one of the two box	kes below.					
	☐ My organization has previously sold or transferred one or more of the affected flex endoscopes to a third party, and I have forwarded the "Urgent Medical Device Rec Notice" to all such third parties.						
	My organization has in a third party.	not sold or transferred any of the affected flexible endoscopes to					
		Contact Information:					
	Facility Name						
	Address						
Con	tact Person & Title						
	Signature						
	Phone						
	Email						



# APPENDIX Affected Endoscopes and Reprocessing Methods

X = Method Not Acceptable and ✓ = Method Acceptable

	Scope Kit Number	Product Description	Current IFU	Affected Reprocessing Methods	
Scope Base Part Number				All High-Level Disinfection	Liquid Chemical Sterilization (STERIS System 1E)
11272C1	N/A	Flexible Cysto-Urethroscope Fiberscope	Z18449US-BD (08-2018)	Х	X
11272C2	11272CK2	Flexible Cystoscope	Z18449US-BD (08-2018)	х	X
11272CU1	11272CUK1	Flexible Cystoscope	Z18449US-BD (08-2018)	Х	X
11272V	N/A	Flexible CMOS Video Cysto Urethroscope	Z18446US-BE (01/2020)	х	Х
11272VA	11272VAK	Flexible CMOS Video Cysto Urethroscope	Z18446US-BE (01/2020)	Х	Х
11272VH-TL	11272VHK-TL	HD-VIEW Flexible HD Cysto-Urethroscope	Z23875US-BC (10-2021)	Х	Х
11272VHU-TL	11272VHUK-TL	HD-VIEW Flexible HD Cysto-Urethroscope	Z23875US-BC (10-2021)	Х	Х
11272VN	11272VNK	Flexible Video Urethro Cystoscope	Z18442US-BD (08/2018)	Х	Х
11272VNU	11272VNUK	Flexible Video Urethro Cystoscope	Z18442US-BD (08/2018)	Х	Х
11272VU	11272VUK	Flexible CMOS Video Cysto Urethroscope	Z18446US-BE (01/2020)	х	Х
11272VUA	11272VUAK	Flexible CMOS Video Cysto Urethroscope	Z18446US-BE (01/2020)	Х	Х
11272VUE	11272VUEK	Flexible Video Cysto-Urethroscope	96136031USCA V1.1 (04/2021)	Х	Х
11272VUE-R	11272VUEK-R	Flexible Video Cysto-Urethroscope	96136031USCA V1.1 (04/2021)	Х	Х
11274BCU1	11274BCUK1	Flexible Cystoscope	Z18449US-BD (08-2018)	Х	Х
11278A2	11278AK2	Flexible Ureteroscope	Z20615US-BA (08-2018)	Х	Х
11278AC1	N/A	Flexible Ureteroscope	Z17859US-A (04/2016)	Х	Х
11278AC2	11278ACK2	Flexible Ureteroscope	Z20615US-BA (08-2018)	х	Х
11278ACU1	11278ACUK1	Flexible Ureteroscope	Z20615US-BA (08-2018)	х	Х



# APPENDIX Affected Endoscopes and Reprocessing Methods

X = Method Not Acceptable and ✓ = Method Acceptable

	Scope Kit Number	Product Description	Current IFU	Affected Reprocessing Methods	
Scope Base Part Number				All High-Level Disinfection	Liquid Chemical Sterilization (STERIS System 1E)
11278AU1	11278AUK1	Flexible Ureteroscope	Z20615US-BA (08-2018)	Х	X
11278V	11278VK	CMOS Video Ureteroscope	Z17744US-A (04/2016)	Х	<b>✓</b>
11278VA	11278VAK	Flexible Video-Uretero-Renoscope (FLEX-XC)	Z23117US-BA (10/2020)	Х	<b>✓</b>
11278VSA	11278VSAK	Flexible Video-Uretero-Renoscope (FLEX-XC)	Z23117US-BA (10/2020)	Х	<b>✓</b>
11278VSE	11278VSEK	Flexible Video-Uretero-Renoscope (FLEX-XC)	Z23117US-BA (10/2020)	Х	✓
11278VSU	11278VSUK	Flexible Video-Uretero-Renoscope (FLEX-XC)	Z18447US-BC (03/2018)	Х	<b>✓</b>
11278VSUA	11278VSUAK	Flexible Video-Uretero-Renoscope (FLEX-XC)	Z23117US-BA (10/2020)	Х	✓
11278VSUE	11278VSUEK	Flexible Video-Uretero-Renoscope (FLEX-XC)	Z23117US-BA (10/2020)	Х	<b>√</b>
11278VU	11278VUK	Flexible Video-Uretero-Renoscope (FLEX-XC)	Z18447US-BC (03/2018)	Х	✓
11278VUA	11278VUAK	Flexible Video-Uretero-Renoscope (FLEX-XC)	Z23117US-BA (10/2020)	Х	<b>✓</b>